

FIG.1
(PRIOR ART)




FIG.2
(PRIOR ART)




FIG.3
(PRIOR ART)




FIG.4
(PRIOR ART)




FIG.5
(PRIOR ART)




FIG.6
(PRIOR ART)




FIG.7A
PRIOR ART



FIG.7B
PRIOR ART




FIG.7C
PRIOR ART




FIG.7D
PRIOR ART




FIG.7E
PRIOR ART




FIG.8
PRIOR ART




FIG.9




FIG.10




FIG.11A




FIG.11B




FIG.13




FIG.14




FIG.15A




FIG.15B




FIG.15C




FIG.15D




FIG.15E



FIG.16A




FIG.16B




FIG.16C




FIG.16D




FIG.16E




FIG.17A




FIG.17B




FIG.18




FIG.19A




FIG.19B




FIG.20




FIG.21




FIG.22A




FIG.22B




FIG.22C




FIG.22D




FIG.22E




FIG.22F




FIG.22G




FIG.23A



FIG.23B





FIG.23C



10073304.024902

FIG.24A




FIG.24B




FIG.25A




FIG.25B




FIG.25C




FIG.25D





FIG.25E



20250402 10:33:04

FIG.26




FIG.27A




FIG.27B




FIG.28




FIG.29A




FIG.29B




FIG.29C




FIG.29D




FIG.29E




FIG.30A




FIG.30B




FIG.31




FIG.32




FIG.33




FIG.34




FIG.35




FIG.36A




FIG.36B




FIG.36C




FIG.36D




FIG.36E




FIG.36F




FIG.37A




FIG.37B




FIG.37C




FIG.37D




FIG.37E




FIG.38




FIG.39







FIG.40



















2023-10-27 10:23:00

FIG.41



CROSS SECTION
ALONG LINE 1306

CROSS SECTION
ALONG LINE 1309



















FIG.44A




FIG.44B




FIG.45




FIG.46




FIG.47




FIG.48A




FIG.48B




FIG.48C




FIG.48D




FIG.48E




FIG.49




FIG.50




FIG.51





FIG.52



10073304.021302
2022.04.20





FIG.54



2025-07-20 10:20:00